MSOP PSS Configuration for C5.5.0-SEQ-000-SEQ.tar Date: 02 Oct 98 - M98 - Delivery Only - (Seggen Adaptation Files) 1. Introduction GDS Delivery Version: **C5.5** ☐ Initial Delivery ☐ Redelivery ICA #: 10272 Spacecraft: ☐ MGS ☐ M98 Orbiter ☐ M98 Lander ☐ Stardust ☐ Other [] □ Block Updates * ☐ Utilities ☐ Command Dictionary Type: Modeling Updates Other [] Notice: Times Below were decided at the Change Board. Installation Window: Best Times to Install: Freeze Times: Comments: Install On same machines as C5.4.0 delivery MCR's 301 - GDS C5.5 - MCO Mapping Block Delivery * M98 Orbiter Mapping Blocks deploy_hga.blk deploy_hga_atlo.blk dsn_contact_map.blk dsn contact relay.blk map_init.blk park_hga.blk pmirr desat tlm.blk sa rewind.blk uhf_cmd_relay.blk uhf_cmd_xband.blk uhf_tlm_only.blk 2. Delivery Location: mgcm1:/staging/MSOP/seq 3. SEQ Workstations - Installation Instructions: \(\subseteq\) N/A \(\xit \) (See Attached - Directory Listing) a) Install - Tar file: C5.5.0-SEQ-000-SEQ.tar - in directory: /msop/seq/ On: X PST Workstations 1) copy the tarfile: **C5.5.0**-SEQ-**000**-SEQ.tar to directory: /msop 2) tar -xvf C5.5.0-SEQ-000-SEQ.tar 3) rm **C5.5.0-**SEQ-**000**-SEQ.tar

Install on mgseq4 only

Comments:

when Install is completed.
 Software Dev will configure /msop/seq_data and other areas clean-out /engineering verify software installed correctly run test cases
2) Software Dev will Notify: SIE on Duty SCM - when configuration is completed.
Special - User's - Alerts - After Install:
 □ Log off workstation - then Log back on (files need to be re-configured) □ Incon's MUST be updated □ Previous symout can be used □ Default - symout MUST be used
Comments: M98 - Delivery Only - (Seqgen Adaptation Files)
4. SCT Workstations - Installation Instructions: □ N/A ☑ (See Attached - Directory Listing) a) Special Alerts - Before Install
Comments:
b) Install Tar file: C5.5.0-SEQ-000-SEQ.tar - in directory: /msop/seq
On: LMA SCT Server LMA STL Workstations Stardust MSA
On: LMA SCT Server LMA STL Workstations Stardust MSA Comments: Ben Jai knows which machines the software should be installed on
Comments: Ben Jai knows which machines the software should be installed on c) Notify: J. Morris (4-1069) S. Wissler (4-0153) Linda Lee (3-9568)
Comments: Ben Jai knows which machines the software should be installed on c) Notify: J. Morris (4-1069) S. Wissler (4-0153) Linda Lee (3-9568) when Install is completed. 1) Software Dev will configure /msop/seq_data and other areas clean-out /engineering verify software installed correctly
Comments: Ben Jai knows which machines the software should be installed on c) Notify: J. Morris (4-1069) S. Wissler (4-0153) Linda Lee (3-9568) when Install is completed. 1) Software Dev will configure /msop/seq_data and other areas clean-out /engineering verify software installed correctly run test cases
Comments: Ben Jai knows which machines the software should be installed on c) Notify: J. Morris (4-1069) S. Wissler (4-0153) Linda Lee (3-9568) when Install is completed. 1) Software Dev will configure /msop/seq_data and other areas lean-out /engineering verify software installed correctly run test cases 2) Software Dev will Notify: ACE CM - when configuration is completed.

CM_delivery.dot 2 10/02/98

5.0 SOPC/ER Workstations - Installation Instructions: □ N/A □ (See Attached - Directory Listing)
a) Install - Tar file: C5.5.0-SEQ-000-SEQ.tar - in directory: /msop/seq/
On: MGS - SOPC Workstations MSOP - SOPC Workstations MSOP SOPC Workstations
 copy the tarfile: C5.5.0-SEQ-000 -SEQ.tar to /msop tar -xvf C5.5.0-SEQ-000 -SEQ.tar rm C5.5.0-SEQ-000 -SEQ.tar
Comments:
b) Notify: ☐ J. Morris (4-1069) ☐ S. Wissler (4-0153) ☐ Linda Lee (3-9568) when Install is completed.
 Software Dev will configure /msop/seq_data and other areas clean-out /engineering verify software installed correctly run test cases
2) Software Dev will Notify: ⊠ J. Glance (3-0630) ⊠ CM - when configuration is completed.
Special - User's - Alerts - After Install -
□ Log off workstation - then Log back on (files need to be re-configured)
Comments: M98 - Delivery Only - (Seqgen Adaptation Files)
Notice: In the event there is a problem with a SOPC/ER Workstation install, notify Jesse Glance (3-0630) or his Pager # (818) 541-5702
This form will be placed on our homepage, in the following URL: http://mgsw3.jpl.nasa.gov/seq/seq_dev/
Directory Listing: C5.5.0-SEQ-000 -SEQ.tar
0 Oct 1 21:57 1998 seq/
0 Oct 1 23:08 1998 seq/satf/ 211547 Oct 1 23:01 1998 seq/satf/M98.orbiter.B36.satf
0 Oct 1 23:06 1998 seq/bin/
8321 Oct 1 23:05 1998 seq/bin/msop-seq-setup 0 Oct 1 22:00 1998 seq/cvf/
0 Oct 1 22:00 1998 seq/cvf/ 18128 Oct 1 00:17 1998 seq/cvf/M98.orbiter.A16.cvf

CM_delivery.dot 3 10/02/98